Baldwin Hardware Manufacturing Corporation 841 East Wyomissing Boulevard, Reading, Pennsylvania



Date 07.08.2003

Gravel Area East of Building 12

View Direction NW

Description

Loading Dock Area: Dock #5 and Dock #6 (Open Bay-Door)

Baldwin Hardware Manufacturing Corporation 841 East Wyomissing Boulevard, Reading, Pennsylvania



DateViewpointView DirectionDescription07.08.2003Gravel Area East of Building 12NLoading Dock #6. Note Dust Tracks on Concrete Floor of Buffing Dust Handling and Storage Area of Building 12

Baldwin Hardware Manufacturing Corporation 841 East Wyomissing Boulevard, Reading, Pennsylvania



Date 07.08.2003

ViewpointEast of Building 10 and South of
Building 12

View Direction

etion Description

W

Groundwater Pump-and-Treat System Air Stripper

PHOTODOCUMENTATION
Baldwin Hardware Manufacturing Corporation
841 East Wyomissing Boulevard, Reading, Pennsylvania



Date

ViewpointEast of Building 10 and South of
Building 12

View Direction

E/NE

Description

Groundwater Pump-and-Treat System Air Stripper

Baldwin Hardware Manufacturing Corporation 841 East Wyomissing Boulevard, Reading, Pennsylvania



Date 07.08.2003

Viewpoint


View Direction

Description
Plant Production Well Pumps (Plant Clear
Well to the Right of Photograph)

East of Building 10 and South of Building 12

N

Baldwin Hardware Manufacturing Corporation 841 East Wyomissing Boulevard, Reading, Pennsylvania



Date 07.08.2003


Viewpoint

View Direction

DescriptionWWTP Components. Note Liquid/Staining in Concrete Trench.

WWTP Basement

Baldwin Hardware Manufacturing Corporation 841 East Wyomissing Boulevard, Reading, Pennsylvania



Date 07.08.2003

ViewpointWWTP Basement

View Direction

DescriptionWWTP Components

Baldwin Hardware Manufacturing Corporation 841 East Wyomissing Boulevard, Reading, Pennsylvania



Date 07.08.2003

ViewpointWWTP Basement

View Direction

DescriptionRusted Base of Door

Baldwin Hardware Manufacturing Corporation 841 East Wyomissing Boulevard, Reading, Pennsylvania




Date 07.08.2003

ViewpointWWTP Basement

View Direction

DescriptionRusted Component of Treatment Tank

Baldwin Hardware Manufacturing Corporation 841 East Wyomissing Boulevard, Reading, Pennsylvania



Date 07.08.2003

ViewpointWWTP Basement

View Direction

DescriptionWWTP Components. Note Staining on Far Wall.